
**TRANSPORTATION SAFETY BOARD OF CANADA
DAILY NOTIFICATION LOG
MODE: RAIL**

Report Date: 24-Oct-2006

Entry Date From: 21-Oct-2006 To: 21-Oct-2006

This Information is preliminary and subject to change. Further, the information given for some occurrences may not have been verified by the TSB. Therefore, caution should be used when using this information.

-----*Occurrence 1*-----

Occurrence No. :	R06T0252	Occurrence Type:	ACCIDENT
Class :	5	Accident/Incident Type:	NON-MAIN-TRACK TRAIN DERAILMENT
Date :	2006-10-11	Subdivision Owner:	CANADIAN PACIFIC RAILWAY CO.
Time :	10:50	Subdivision:	BELLEVILLE
Location :	SMITHS FALLS	Mileage:	.1
Province :	ONTARIO	Spur Name:	
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	SMITHS FALLS
		Train Operator:	CANADIAN PACIFIC RAILWAY CO.
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

TRAIN F55-11 REPORTED DERAILING 4 LOADED CARS OF NONDANGEROUS GOODS IN SMITH FALLS YARD. ALL CARS ARE UPRIGHT. THERE WERE NO INJURIES.

-----*Occurrence 2*-----

Occurrence No. :	R06V0214	Occurrence Type:	ACCIDENT
Class :	5	Accident/Incident Type:	NON-MAIN-TRACK TRAIN DERAILMENT
Date :	2006-10-06	Subdivision Owner:	CANADIAN PACIFIC RAILWAY CO.
Time :	00:30	Subdivision:	WESTMINSTER
Location :	VANCOUVER	Mileage:	
Province :	BRITISH COLUMBIA	Spur Name:	MARPOLE
DG Involved :		Spur Mileage:	8.00
DG Released :		Yard Name:	
		Train Operator:	
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

WHILE REVERSING ON THE MARPOLE SPUR THE YARD ASGN REPORTED DERAILING LEAD LOCOMOTIVE CP1239 OVER THE STOP BLOCK. NO INJURY

-----*Occurrence 3*-----

Occurrence No. :	R06V0215	Occurrence Type:	ACCIDENT
Class :	5	Accident/Incident Type:	TRESPASSER
Date :	2006-10-07	Subdivision Owner:	BURLINGTON NORTHERN SANTA FE COMPANY
Time :	10:37	Subdivision:	NEW WESTMINSTER
Location :	STILL CREEK	Mileage:	154.72

Province :	BRITISH COLUMBIA	Spur Name:	
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	
		Train Operator:	BURLINGTON NORTHERN AND SANTA FE MAN INC.
Injuries:	Fatal : 1	Serious : 0	Minor : 0 None

Occurrence Summary :

AFTER TRAIN BNSF6143 HAD PASSED BY, WITNESSES REPORTED THAT A TRESPASSER HAD CRAWLED UNDER THE MOVING TRAIN AND RECEIVED FATAL INJURY.

-----**Occurrence 4**-----

Occurrence No. :	R06W0175	Occurrence Type:	VOLUNTARY
Class :	5	Accident/Incident Type:	
Date :	2006-10-12	Subdivision Owner:	CANADIAN NATIONAL RAILWAY CO.
Time :	16:47	Subdivision:	WATROUS
Location :		Mileage:	
Province :	SASKATCHEWAN	Spur Name:	
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	
		Train Operator:	
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

AFTER TRAIN Q11531-10 DEPARTED SASKATOON, SASK. WITH TGBO 5679, TGBO 5679 WAS CANCELLED IN ERROR. THERE WERE NO OTHER TRAINS IN THE BLOCK.

-----**Occurrence 5**-----

Occurrence No. :	R06W0176	Occurrence Type:	ACCIDENT
Class :	5	Accident/Incident Type:	MAIN-TRACK TRAIN DERAILMENT
Date :	2006-10-11	Subdivision Owner:	HUDSON BAY RAILWAY
Time :	04:15	Subdivision:	THICKET
Location :	WABOWDEN	Mileage:	136.51
Province :	MANITOBA	Spur Name:	
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	
		Train Operator:	HUDSON BAY RAILWAY
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

WHILE PROCEEDING NORTHWARD OVER THE HIGHWAY 61 CROSSING TRAIN 815 REPORTED DERAILING 5 LOADED GRAIN CARS. NO INJURY. NO DANGEROUS GOODS INVOLVED. ALL CARS UPRIGHT.

-----**Occurrence 6**-----

Occurrence No. :	R06V0216	Occurrence Type:	ACCIDENT
Class :	5	Accident/Incident Type:	R/S COLL. WITH OBJECT
Date :	2006-10-11	Subdivision Owner:	SOUTHERN RAILWAY VANCOUVER ISLAND
Time :	10:45	Subdivision:	VICTORIA
Location :	LADYSMITH	Mileage:	65.4
Province :	BRITISH COLUMBIA	Spur Name:	
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	
		Train Operator:	VIA RAIL CANADA INC.
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

WHILE TRAVELLING AT APPROX 25 MPH TRAIN VIA 199 REPORTED STRIKING ROCKS BETWEEN THE RAILS . VIA 6135 RECEIVED DAMAGE TO THE PILOTS , UNDER CARRIAGE, STEPS, TRANSMISSION AND FUEL SYSTEM. LOCAL FIRE DEPT CONTAINED LEAK WITH LEAK PADS AND DRIP PAN. NANAIMO RCMP INVESTIGATING REPORT OF A DUMP TRUCK DUMPING ROCKS FROM A SITE ABOVE THE TRACKS. NO INJURY REPORTED.

-----Occurrence 7-----

Occurrence No. :	R06W0177	Occurrence Type:	ACCIDENT
Class :	5	Accident/Incident Type:	CROSSING
Date :	2006-10-11	Subdivision Owner:	CANADIAN PACIFIC RAILWAY CO.
Time :	15:48	Subdivision:	WILKIE
Location :	SASKATOON	Mileage:	.79
Province :	SASKATCHEWAN	Spur Name:	
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	
		Train Operator:	
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

WHILE PROCEEDING WITH A LIGHT ENGINE SWITCHING ASGN N49 REPORTED STRIKING A VEHICLE AT A PUBLIC CROSSING EQUIPPED WITH FLASHING SIGNAL LIGHTS AND BELL OPERATING AS INTENDED. NO INJURIES.

-----Occurrence 8-----

Occurrence No. :	R06T0253	Occurrence Type:	INCIDENT
Class :	5	Accident/Incident Type:	MOVEMENT EXCEEDS LIMITS OF AUTHORITY
Date :	2006-10-13	Subdivision Owner:	CANADIAN NATIONAL RAILWAY CO.
Time :	10:26	Subdivision:	RUEL
Location :	ALBANY FORKS	Mileage:	263.4
Province :	ONTARIO	Spur Name:	
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	
		Train Operator:	
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

FOREMAN ON TRACK PATROL WITH TOP BETWEEN OBA WEST AND PENHURST, CANCELLED TOP AFTER CLEARING INTO THE SIDING AT ALBANY FORKS WITHOUT HAVING AUTHORITY TO OCCUPY THE SIDING. THE FOREMAN CALLED THE RTC AND RECEIVED THE AUTHORITY. THERE WERE NO CONFLICTING TRAIN MOVEMENTS. THERE WERE NO INJURIES.

-----Occurrence 9-----

Occurrence No. :	R06T0254	Occurrence Type:	ACCIDENT
Class :	5	Accident/Incident Type:	NON-MAIN-TRACK TRAIN COLLISION
Date :	2006-10-11	Subdivision Owner:	CANADIAN PACIFIC RAILWAY CO.
Time :	22:30	Subdivision:	BELLEVILLE
Location :	AGINCOURT	Mileage:	197
Province :	ONTARIO	Spur Name:	
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	
		Train Operator:	
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

DURING HUMP OPERATIONS, CAR BTTX800040 HUMPED THROUGH TRACK CT47 AND STRUCK YARD ASGN TT23. NO INJURIES. NO DANGEROUS GOODS INVOLVED. CAR BTTX800040, LOAD OF AUTOS, DERAILED. THREE CARS LOADED WITH WAX, TLUX 223012, PTLX223313, GPLX 75937 WERE REPORTED DAMAGED. NO INJURIES REPORTED.

-----Occurrence 10-----

Occurrence No. :	R06C0138	Occurrence Type:	ACCIDENT
Class :	5	Accident/Incident Type:	NON-MAIN-TRACK TRAIN DERAILMENT
Date :	2006-10-13	Subdivision Owner:	CANADIAN PACIFIC RAILWAY CO.
Time :	08:00	Subdivision:	BROOKS
Location :	CALGARY	Mileage:	173
Province :	ALBERTA	Spur Name:	
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	
		Train Operator:	
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

YARD EMPLOYEES IN AYLTH REPORTED THAT EMPTY CARS SRY 286565 AND SRY 286422 WERE DERAILED IN TRACK CT04. A THIRD INVOLVED CAR, CAR GATX 54326, LOAD OF RAPESEED OIL, HAD A DAMAGED CROSS OVER AND APPEARED TO HAVE CROSSED DRAWBARS DURING COUPLING. NO INJURIES, NO DANGEROUS GOODS INVOLVED.

-----Occurrence 11-----

Occurrence No. :	R06C0139	Occurrence Type:	ACCIDENT
Class :	5	Accident/Incident Type:	R/S COLL. WITH OBJECT
Date :	2006-10-17	Subdivision Owner:	CANADIAN PACIFIC RAILWAY CO.
Time :	12:15	Subdivision:	LAGGAN
Location :	CANMORE	Mileage:	69.5
Province :	ALBERTA	Spur Name:	
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	
		Train Operator:	CANADIAN PACIFIC RAILWAY CO.
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

THE CREW FROM TRAIN 101-14 REPORTED SEEING VANDALS PLACING AN OBJECT ON THE TRACK (POSSIBLY A PIECE OF RAIL). THE TRAIN STRUCK THE OBJECT AND SUSTAINED DAMAGE TO ITS BRAKE RIGGING. THERE WAS NO DERAILMENT. THERE WERE NO INJURIES.

-----Occurrence 12-----

Occurrence No. :	R06T0255	Occurrence Type:	ACCIDENT
Class :	5	Accident/Incident Type:	MAIN-TRACK TRAIN DERAILMENT
Date :	2006-10-12	Subdivision Owner:	CANADIAN NATIONAL RAILWAY CO.
Time :	22:05	Subdivision:	BALA
Location :	SUDBURY	Mileage:	205
Province :	ONTARIO	Spur Name:	
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	
		Train Operator:	CANADIAN PACIFIC RAILWAY CO.
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

WHILE PROCEEDING SOUTHWARD ON THE CN BALA SUBDIVISION , CP TRAIN 222-11 REPORTED GOING INTO EMERGENCY. EXAMINATION OF THE TRAIN REVEALED THAT EMPTY CAR CP220444 WAS DERAILED. NO INJURIES. NO DANGEROUS GOODS INVOLVED.

-----Occurrence 13-----

Occurrence No. :	R06T0256	Occurrence Type:	ACCIDENT
Class :	5	Accident/Incident Type:	R/S COLL. WITH OBJECT

Date :	2006-10-13	Subdivision Owner:	CANADIAN PACIFIC RAILWAY CO.
Time :	17:00	Subdivision:	BELLEVILLE
Location :	SMITHS FALLS	Mileage:	11.5
Province :	ONTARIO	Spur Name:	
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	
		Train Operator:	
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

WHILE PROCEEDING EASTWARD TRAIN 234 REPORTED STRIKING A PIECE OF RAIL LEFT BESIDE THE TRACKS AND PUNCTURING THE FUEL TANK ON LOCOMOTIVE CP6009, RESULTING IN APPROX 200 GALS OF FUEL LOSS. CP OFFICIALS AND ENVIRONMENT RESPONDED. NO INJURIES

-----**Occurrence 14**-----

Occurrence No. :	R06W0178	Occurrence Type:	ACCIDENT
Class :	5	Accident/Incident Type:	NON-MAIN-TRACK TRAIN COLLISION
Date :	2006-10-18	Subdivision Owner:	CANADIAN NATIONAL RAILWAY CO.
Time :	02:38	Subdivision:	RIVERS
Location :	MELVILLE	Mileage:	280.3
Province :	SASKATCHEWAN	Spur Name:	
DG Involved :	7	Spur Mileage:	
DG Released :		Yard Name:	MELVILLE
		Train Operator:	
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

AFTER PLACING A CUT OF 4 CARS INTO TRACK MR19, YARD ASSIGNMENT YMYS60-17 WAS PULLING A CUT OF 22 CARS FROM TRACK MR10 ONTO THE LEAD WHEN THE CUT OF 4 CARS RAN UNCONTROLLED. THE LEAD CAR OF THE CUT OF 4 CARS STRUCK THE CARS ON THE LEAD, DAMAGED TEN CARS ON THE LEAD, INCLUDING 7 EMPTY RESIDUE DG CARS (UN1202, UN1075, UN 2448), AND DERAILED. THERE WAS NO LOSS OF PRODUCT. THERE WERE NO INJURIES. CN OFFICIALS RESPONDED.

-----**Occurrence 15**-----

Occurrence No. :	R06V0217	Occurrence Type:	INCIDENT
Class :	5	Accident/Incident Type:	MOVEMENT EXCEEDS LIMITS OF AUTHORITY
Date :	2006-10-14	Subdivision Owner:	CANADIAN PACIFIC RAILWAY CO.
Time :	14:30	Subdivision:	CASCADE
Location :	COQUITLAM	Mileage:	116.1
Province :	BRITISH COLUMBIA	Spur Name:	
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	
		Train Operator:	
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

WHILE PULLING THROUGH TRACK G5 IN COQUITLAM YARD, TRAIN 603 STOPPED AND THEN SET OVER THE MID TRAIN LOCOMOTIVE CP8564 THROUGH THE CROSS-OVER SWITCHES TO THE MAIN TRACK WITHOUT AN AUTHORITY TO OCCUPY THE MAIN TRACK.. NO INJURIES. NO DANGEROUS GOODS INVOLVED.

-----**Occurrence 16**-----

Occurrence No. :	R06E0109	Occurrence Type:	ACCIDENT
Class :	5	Accident/Incident Type:	CROSSING
Date :	2006-10-12	Subdivision Owner:	CANADIAN NATIONAL RAILWAY CO.
Time :	00:45	Subdivision:	EDSON
Location :	EDMONTON	Mileage:	0

Province :	ALBERTA	Spur Name:	L ZONE INDUSTRIAL
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	
		Train Operator:	CANADIAN NATIONAL RAILWAY CO.
Injuries:	Fatal : 0	Serious : 0	Minor : 1 None

Occurrence Summary :

WHILE TRAVELLING NORTHWARD OVER A PUBLIC CROSSING, THE LEAD LOCOMOTIVE ON THE CN 2300 YARD ASSIGNMENT YBS605 (CN 7242), WAS STRUCK BY AN EASTBOUND TRACTOR TRAILER. THE LOCOMOTIVE SUSTAINED DAMAGE BUT THERE WERE NO INJURIES TO RAILWAY PERSONNEL. THE TRUCK DRIVER WAS TRANSPORTED TO HOSPITAL WITH UNDETERMINED INJURY

-----**Occurrence 17**-----

Occurrence No. :	R06W0179	Occurrence Type:	ACCIDENT
Class :	5	Accident/Incident Type:	NON-MAIN-TRACK TRAIN DERAILMENT
Date :	2006-10-15	Subdivision Owner:	CANADIAN PACIFIC RAILWAY CO.
Time :	16:55	Subdivision:	GRAVELBOURG
Location :	HODGEVILLE	Mileage:	52
Province :	SASKATCHEWAN	Spur Name:	SASK WHEAT POOL
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	
		Train Operator:	
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

WHILE PULLING EASTWARD AT THE SASK WHEAT POOL ELEVATOR TRACK AT HODGEVILLE, TRAIN ASGN K31-15 REPORTED DERAILING 3 LOADED GRAIN CARS AT THE WEST ELEVATOR TRACK SWITCH. NO INJURIES. NO DANGEROUS GOODS INVOLVED. NO LOSS OF PRODUCT.

-----**Occurrence 18**-----

Occurrence No. :	R06E0110	Occurrence Type:	ACCIDENT
Class :	5	Accident/Incident Type:	NON-MAIN-TRACK TRAIN DERAILMENT
Date :	2006-10-17	Subdivision Owner:	CANADIAN PACIFIC RAILWAY CO.
Time :	03:50	Subdivision:	LEDUC
Location :	EDMONTON	Mileage:	96.4
Province :	ALBERTA	Spur Name:	
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	SOUTH EDMONTON
		Train Operator:	CANADIAN PACIFIC RAILWAY CO.
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

WHILE MAKING A REVERSE MOVEMENT, PITCH AND CATCH ASSIGNMENT 2230 DERAILED EMPTY CAR ACFX 95647 ON THE NORTH LEAD. THERE WERE NO INJURIES.

-----**Occurrence 19**-----

Occurrence No. :	R06C0140	Occurrence Type:	INCIDENT
Class :	5	Accident/Incident Type:	MAIN-TRACK SWITCH IN ABNORMAL POSITION
Date :	2006-10-12	Subdivision Owner:	CANADIAN PACIFIC RAILWAY CO.
Time :	02:30	Subdivision:	LAGGAN
Location :	CALGARY	Mileage:	9.6
Province :	ALBERTA	Spur Name:	
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	
		Train Operator:	

Injuries:	Fatal : 0	Serious : 0	Minor : 0	None
------------------	-----------	-------------	-----------	------

Occurrence Summary :

CP RTC REPORTED A UTO AT THE SOUTH KEITH YARD SWITCH. SUBSEQUENT INSPECTION BY SIGNAL MAINTAINER REVEALED THAT THE SWITCH WAS LEFT OPEN, IN THE REVERSE POSITION.

-----**Occurrence 20**-----

Occurrence No. :	R06C0141	Occurrence Type:	INCIDENT	
Class :	5	Accident/Incident Type:	MOVEMENT EXCEEDS LIMITS OF AUTHORITY	
Date :	2006-10-15	Subdivision Owner:	CANADIAN PACIFIC RAILWAY CO.	
Time :	18:50	Subdivision:	LAGGAN	
Location :	KEITH	Mileage:	9.6	
Province :	ALBERTA	Spur Name:		
DG Involved :		Spur Mileage:		
DG Released :		Yard Name:		
		Train Operator:		
Injuries:	Fatal : 0	Serious : 0	Minor : 0	None

Occurrence Summary :

WHILE STOPPING ON THE MAIN TRACK AT KEITH, EASTWARD TRAIN 470 CLEARED THE WEST POWER SWITCH CIRCUIT AND WHEN THE BUNCHED SLACK ROLLED OUT WESTWARD THE REAR END CAR FOULED THE CIRCUIT. NO INJURIES. NO DANGEROUS GOODS INVOLVED.

-----**Occurrence 21**-----

Occurrence No. :	R06H0015	Occurrence Type:	ACCIDENT	
Class :	5	Accident/Incident Type:	NON-MAIN-TRACK TRAIN DERAILMENT	
Date :	2006-10-17	Subdivision Owner:	OTTAWA VALLEY RAILWAY	
Time :	20:05	Subdivision:	NORTH BAY	
Location :	MATTAWA	Mileage:	72.11	
Province :	ONTARIO	Spur Name:		
DG Involved :		Spur Mileage:		
DG Released :		Yard Name:		
		Train Operator:	OTTAWA VALLEY RAILWAY	
Injuries:	Fatal : 0	Serious : 0	Minor : 0	None

Occurrence Summary :

WHILE SWITCHING WITH LIGHT ENGINES, OVR TRAIN 220-11 DERAILED 2 LOCOMOTIVES IN THE BACK TRACK AT MILE 72.11 OF THE NORTH BAY SUBDIVISION. THERE WERE NO INJURIES.

-----**Occurrence 22**-----

Occurrence No. :	R06C0142	Occurrence Type:	ACCIDENT	
Class :	5	Accident/Incident Type:	MAIN-TRACK TRAIN DERAILMENT	
Date :	2006-10-16	Subdivision Owner:	CANADIAN PACIFIC RAILWAY CO.	
Time :	07:00	Subdivision:	WINDERMERE	
Location :	FORT STEELE	Mileage:	.44	
Province :	BRITISH COLUMBIA	Spur Name:		
DG Involved :		Spur Mileage:		
DG Released :		Yard Name:		
		Train Operator:		
Injuries:	Fatal : 0	Serious : 0	Minor : 0	None

Occurrence Summary :

WHILE PERFORMING TRACK MAINTENANCE AT FORT STEELE, THE RAIL GRINDER TRAIN RG310 REPORTED DERAILING TWO GRINDING PLATFORMS AT THE SOUTH MAIN TRACK SWITCH. APPROX 50 LITRES OF HYDRAULIC FLUID LEAKED. NO WATERWAYS AFFECTED. NO INJURIES.

-----Occurrence 23-----

Occurrence No. :	R06T0257	Occurrence Type:	ACCIDENT
Class :	5	Accident/Incident Type:	MAIN-TRACK TRAIN DERAILMENT
Date :	2006-10-12	Subdivision Owner:	CANADIAN NATIONAL RAILWAY CO.
Time :	22:20	Subdivision:	BALA
Location :	SUDBURY	Mileage:	205
Province :	ONTARIO	Spur Name:	
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	
		Train Operator:	CANADIAN PACIFIC RAILWAY CO.
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

CP TRAIN 222-11, PROCEEDING SOUTHWARD ON THE CN BALA SUBDIVISION, DERAILED EMPTY BOX CAR CP 220444 AT MILE 205.0. THERE WERE NO INJURIES AND NO DANGEROUS GOODS INVOLVED.

-----Occurrence 24-----

Occurrence No. :	R06W0180	Occurrence Type:	ACCIDENT
Class :	5	Accident/Incident Type:	CROSSING
Date :	2006-10-16	Subdivision Owner:	CANADIAN NATIONAL RAILWAY CO.
Time :	17:05	Subdivision:	PREECEVILLE
Location :	BENITO	Mileage:	19
Province :	MANITOBA	Spur Name:	
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	
		Train Operator:	
Injuries:	Fatal : 0	Serious : 0	Minor : 1 None

Occurrence Summary :

WHILE PROCEEDING EASTWARD AT SWAN RIVER, TRAIN 588 REPORTED STRIKING A VEHICLE AT A PUBLIC CROSSING. MINOR INJURIES RREPORTED TO THE LONE VEHICLE OCCUPANT

-----Occurrence 25-----

Occurrence No. :	R06W0181	Occurrence Type:	INCIDENT
Class :	5	Accident/Incident Type:	MOVEMENT EXCEEDS LIMITS OF AUTHORITY
Date :	2006-10-15	Subdivision Owner:	CANADIAN NATIONAL RAILWAY CO.
Time :	16:30	Subdivision:	WATROUS
Location :	JASMIN	Mileage:	42.4
Province :	SASKATCHEWAN	Spur Name:	
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	
		Train Operator:	CANADIAN NATIONAL RAILWAY CO.
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

WHILE PROCEEDING EASTWARD ON THE WATROUS SUB TRAIN Q10451-13 REPORTED THAT THEIR TGBO WAS ADDRESSED TO TRAIN Q10451-31. THE TGBO DESIGNATION WAS CHANGED TO REFLECT PROPER TRAIN DESIGNATION.

-----Occurrence 26-----

Occurrence No. :	R06C0143	Occurrence Type:	ACCIDENT
Class :	5	Accident/Incident Type:	NON-MAIN-TRACK TRAIN DERAILMENT
Date :	2006-10-12	Subdivision Owner:	CANADIAN PACIFIC RAILWAY CO.

Time :	19:55	Subdivision:	BROOKS
Location :	CALGARY	Mileage:	174.1
Province :	ALBERTA	Spur Name:	
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	ALYTH
		Train Operator:	CANADIAN PACIFIC RAILWAY CO.
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

CP REPORTED THAT TRAIN 478-11 DERAILED EMPTY COVERED HOPPER CAR CEFX 635926 AT THE WEST END OF THE YARD LEAD. THERE WERE NO INJURIES AND NO DANGEROUS GOODS INVOLVED.

-----**Occurrence 27**-----

Occurrence No. :	R06E0111	Occurrence Type:	VOLUNTARY
Class :	5	Accident/Incident Type:	
Date :	2006-10-18	Subdivision Owner:	CANADIAN PACIFIC RAILWAY CO.
Time :	02:20	Subdivision:	WETASKIWIN
Location :	CAMROSE	Mileage:	75
Province :	ALBERTA	Spur Name:	
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	
		Train Operator:	
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

CP EMPLOYEES REPORTED SEEING COVERED HOPPER CAR EEC 61860 DERAILED ON THE ERVICK ELEVATOR TRACK.

-----**Occurrence 28**-----

Occurrence No. :	R06W0182	Occurrence Type:	ACCIDENT
Class :	5	Accident/Incident Type:	NON-MAIN-TRACK TRAIN DERAILMENT
Date :	2006-10-12	Subdivision Owner:	CANADIAN PACIFIC RAILWAY CO.
Time :	19:30	Subdivision:	NIPIGON
Location :	THUNDER BAY	Mileage:	130
Province :	ONTARIO	Spur Name:	
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	
		Train Operator:	
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

WHILE SWITCHING IN KEEFER TERMINAL AT THUNDER BAY, THE 0730 YARD ASGN REPORTED DERAILING THE 2ND LOCOMOTIVE CP1160 AND CAR CP 214522,, LOAD OF WOODPULP. NO INJURIES. NO DANGEROUS GOODS INVOLVED.

-----**Occurrence 29**-----

Occurrence No. :	R06T0259	Occurrence Type:	ACCIDENT
Class :	5	Accident/Incident Type:	TRESPASSER
Date :	2006-10-18	Subdivision Owner:	CANADIAN PACIFIC RAILWAY CO.
Time :	09:45	Subdivision:	HAMILTON
Location :	HAMILTON	Mileage:	49.7
Province :	ONTARIO	Spur Name:	
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	
		Train Operator:	CANADIAN PACIFIC RAILWAY CO.
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

TRAIN 255-17 PROCEEDING NORTHWARD REPORTED CONTACTING A TRESPASSER LAYING ON THE RAILWAY RIGHT OF WAY. TRESPASSER WAS CONFIRMED DECEASED.

-----**Occurrence 30**-----

Occurrence No. :	R06V0218	Occurrence Type:	ACCIDENT
Class :	5	Accident/Incident Type:	FIRE
Date :	2006-10-06	Subdivision Owner:	CANADIAN NATIONAL RAILWAY CO.
Time :	17:55	Subdivision:	CHETWYND
Location :	PRINCE GEORGE	Mileage:	513
Province :	BRITISH COLUMBIA	Spur Name:	
DG Involved :	3	Spur Mileage:	
DG Released :		Yard Name:	
		Train Operator:	
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

WHILE PROCEEDING SOUTHWARD TRAIN A47251-06 REPORTED THREE CARS OF SULPHUR SMOKING ON HEAD END OF TRAIN. BEAR LAKE FIRE DEPT EVACUATED SEVERAL HOMES IN THE AREA AND CLOSED HWY 97 FOR APPROX 45 MINUTES. NO INJURIES REPORTED.

-----**Occurrence 31**-----

Occurrence No. :	R06T0260	Occurrence Type:	ACCIDENT
Class :	5	Accident/Incident Type:	NON-MAIN-TRACK TRAIN DERAILMENT
Date :	2006-10-18	Subdivision Owner:	CANADIAN PACIFIC RAILWAY CO.
Time :	20:20	Subdivision:	HAMILTON
Location :	HAMILTON	Mileage:	58.6
Province :	ONTARIO	Spur Name:	
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	ABERDEEN
		Train Operator:	CANADIAN PACIFIC RAILWAY CO.
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

WHILE SHOVING 17 CARS INTO THE SOUTH YARD, CP YARD ASSIGNMENT TH21-18 DERAILED 2 EMPTY FLAT CARS. THERE WERE NO INJURIES AND NO DANGEROUS GOODS WERE INVOLVED.

-----**Occurrence 32**-----

Occurrence No. :	R06E0112	Occurrence Type:	ACCIDENT
Class :	5	Accident/Incident Type:	CROSSING
Date :	2006-10-17	Subdivision Owner:	CANADIAN NATIONAL RAILWAY CO.
Time :	22:35	Subdivision:	VEGREVILLE
Location :	SCOTFORD	Mileage:	.33
Province :	ALBERTA	Spur Name:	FORT SASK INDUSTRIAL
DG Involved :		Spur Mileage:	0.21
DG Released :		Yard Name:	
		Train Operator:	
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

WHILE PROCEEDING EASTWARD IN THE FORT SASKATCHEWAN INDUSTRIAL LEAD, THE SCOTFORD YARD ASGN REPORTED STRIKING A VEHICLE AT A PUBLIC CROSSING EQUIPPED WITH SRCS. NO DAMAGE TO EQUIPMENT . NO INJURIES.

-----Occurrence 33-----

Occurrence No. :	R06C0144	Occurrence Type:	INCIDENT
Class :	5	Accident/Incident Type:	MOVEMENT EXCEEDS LIMITS OF AUTHORITY
Date :	2006-10-18	Subdivision Owner:	CANADIAN PACIFIC RAILWAY CO.
Time :	20:20	Subdivision:	CROWSNEST
Location :	LETHBRIDGE	Mileage:	31.8
Province :	ALBERTA	Spur Name:	
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	
		Train Operator:	CANADIAN PACIFIC RAILWAY CO.
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

WHILE TAKING THE SIDING AT FORT MACLEOD, CP TRAIN 681-030 PULLED UP FOUL OF THE MAIN TRACK WITHOUT PROPER AUTHORITY. THERE WERE NO INJURIES AND NO CONFLICTING MOVEMENTS.

-----Occurrence 34-----

Occurrence No. :	R06W0183	Occurrence Type:	ACCIDENT
Class :	5	Accident/Incident Type:	NON-MAIN-TRACK TRAIN DERAILMENT
Date :	2006-10-19	Subdivision Owner:	CANADIAN PACIFIC RAILWAY CO.
Time :	00:45	Subdivision:	NAPINKA
Location :	BOISSEVAIN	Mileage:	69.97
Province :	MANITOBA	Spur Name:	
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	
		Train Operator:	CANADIAN PACIFIC RAILWAY CO.
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

WHILE SHOVING INTO ELEVATOR TRACK V7501 WITH 3 LOCOMOTIVES AND 5 CARS, CP TRAIN P36-18 DERAILED 1 WHEEL OF THE LEAD LOCOMOTIVE (CP 3082) BLOCKING PROVINCIAL HIGHWAY # 10. THERE WERE NO INJURIES.

-----Occurrence 35-----

Occurrence No. :	R06V0219	Occurrence Type:	INCIDENT
Class :	5	Accident/Incident Type:	MOVEMENT EXCEEDS LIMITS OF AUTHORITY
Date :	2006-10-19	Subdivision Owner:	CANADIAN NATIONAL RAILWAY CO.
Time :	18:26	Subdivision:	ROBSON
Location :	MCCABE	Mileage:	22.7
Province :	BRITISH COLUMBIA	Spur Name:	
DG Involved :		Spur Mileage:	
DG Released :		Yard Name:	
		Train Operator:	CANADIAN NATIONAL RAILWAY CO.
Injuries:	Fatal : 0	Serious : 0	Minor : 0 None

Occurrence Summary :

CN REPORTED THAT TRAIN CN M30351-19 PASSED SIGNAL 227S INDICATING STOP AFTER THE RTC HAD CHANGED THE SIGNAL INDICATION. THERE WERE NO INJURIES AND NO CONFLICTING MOVEMENTS.